TP0@62 022159.

PATENT

NOV 1 6 2007

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

	: Examiner: R. Patel
SEIJI KUROKAMI, et al.)
	: Group Art Unit: 2838
Appl. No.: 09/818,604)

Filed: March 28, 2001)

For: POWER CONVERTING
APPARATUS, CONTROL
METHOD THEREFOR, AND
SOLAR POWER GENERATION
APPARATUS

U.S. Patent No.: 7,079,406 B2 November 15, 2007

Issued: July 18, 2006)

Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450 OF COFFECTION

REQUEST FOR CERTIFICATE OF CORRECTION <u>UNDER RULES 322 AND 323</u>

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form, in duplicate, is enclosed.

Accompanying this letter is a check for \$100.00 to cover the statutory fee for such Certificate of Correction.

11/19/2007 JADDO1

00000065 7079406

01 FC:1811

100.00 09

Patentees' undersigned attorney may be reached in our Costa Mesa, California office by telephone at (714) 540-8700. All correspondence should continue to be directed to our address given below.

Respectfully submitted,

Frank L. Cire

Attorney for Patentees Registration No.: 42,419

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3800 Facsimile: (212) 218-2200

FCHS_WS 852199v1

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO.

7,079,406 B2

DATED

July 18, 2006

INVENTOR(S) :

Seiji Kurokami, et al.

Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COVER PAGE:

(56) References Cited, FOREIGN PATENT DOCUMENTS

"09 084254" should read -- 09-084254 --;

"09 285015" should read -- 09-285015 --; and

"2000 023371" should read -- 2000-023371 --.

COLUMN 2:

Line 29, "a, DC" should read -- a DC --.

COLUMN 3:

Lines 17 and 47, "(an" should read -- (a --.

COLUMN 5:

Line 57, "(an" should read -- (a --.

COLUMN 9:

Line 32, "to-the" should read -- to the --.

COLUMN 10:

Line 13, "(an" should read -- (a --.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3800 (212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82) 124821 (Form#30)

PATENT NO. <u>7,079,406 B2</u>

No. of add'l. copies @ 30¢ per page

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO.

7,079,406 B2

DATED

July 18, 2006

INVENTOR(S) :

Seiji Kurokami, et al.

Page 2 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 11:

Line 57, "lager" should read -- larger --.

COLUMN 12:

Line 27, "(an" should read -- (a --.

COLUMN 18:

Line 20, "Ti" should read -- T1 --; and

Line 37, insert a paragraph break before "con-".

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3800 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile PATENT NO. <u>7,079,406 B2</u>

No. of add'l. copies @ 30¢ per page

11511 27 2017

 \Box

Form PTO 1050 (Rev. 3-82) 124821 (Form#30)

Staple Here Only!

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO.

7,079,406 B2

DATED

July 18, 2006

INVENTOR(S) :

Seiji Kurokami, et al.

Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COVER PAGE:

(56) References Cited, FOREIGN PATENT DOCUMENTS

"09 084254" should read -- 09-084254 --;

"09 285015" should read -- 09-285015 --; and

"2000 023371" should read -- 2000-023371 --.

COLUMN 2:

Line 29, "a, DC" should read -- a DC --.

COLUMN 3:

Lines 17 and 47, "(an" should read -- (a --.

COLUMN 5:

Line 57, "(an" should read -- (a --.

COLUMN 9:

Line 32, "to-the" should read -- to the --.

COLUMN 10:

Line 13, "(an" should read -- (a --.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3800 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile

NOV 27 2007

PATENT NO. <u>7,079,406 B2</u>

No. of add'l. copies @ 30¢ per page

Form PTO 1050 (Rev. 3-82) 124821 (Form#30)

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO.

7,079,406 B2

DATED

July 18, 2006

INVENTOR(S) :

Seiji Kurokami, et al.

Page 2 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 11:

Line 57, "lager" should read -- larger --.

COLUMN 12:

Line 27, "(an" should read -- (a --.

COLUMN 18:

Line 20, "Ti" should read -- T1 --; and Line 37, insert a paragraph break before "con-".

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

NOV 27 2007 ⇒

PATENT NO. <u>7,079,406 B2</u>

No. of add'l. copies @ 30¢ per page

Form PTO 1050 (Rev. 3-82) 124821 (Form#30)